

DELHI JAL BOARD: GOVT. OF NCT OF DELHI
OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)
ROOM NO. 209, VARUNALAYA PHASE-I
KAROL BAGH, NEW DELHI - 110005
23558264

DATED: 16/5/19

No./DJB/EE(RWH/GWC)/2019/2703

To,

The Principal,
S.S. Khalsa Sr. Sec. School (Chakwal),
Lajpat Nagar-IV, New Delhi-24


Subject:-Regarding adequacy of rain water harvesting system at S.S. Khalsa
Sr. Sec. School (Chakwal), Lajpat Nagar-IV, New Delhi-24.

Sir/Madam,

The above said unit has been inspected by Joint Inspection Team on dated 16.05.2019, constituted by Hon'ble NGT in O.A. No. 217/2016. It was found that one No. RWH pit is existing at site.

The existing RWH structure is adequate to harvest the roof top run-off for catchment area of above said unit. The RWH structure was found to be functional at the time of inspection.

You are advised to keep the existing RWH system neat & clean & maintain the same periodically. Rain Water conveyance system shall be duly kept connected to RWH pits and filter media shall be maintained and kept neat & clean, as per DJB norms and over flow shall always remain connected to municipal drain.


EE (RWH/GWC)

EE (G W CELL)
DELHI
VARUNALAYA BHAWAN,
JHANEWALLAN, N.D.-05